

Townships N 6 & 7 North, Range N 13 East.


Pests	Bearing true	Inches diam	Course true bear	Links dist	Qualif.
A Sugar Buck		9	S 2 W	21	From A to B
a		13	S 35 W	22	
B Hickory Dogwood		13	S 30 W	23	" B to C
C W Oak		13	S 23 E	12	
W Oak		16	S 81 W	30	
D Sugar		3	S 30 W	10	
Sugar		14	S 12 E	20	
E Poplar		16	Corner		
F W Oak		14	Corner		
G B Oak		24	Corner		
H Buck		6	S 75 W	35	
I W Oak		24	S 40 W	22	
Buck		14	S 70 E	32	
K Buckeye		7	S 75 W	23	
Hickory		3	S 52 E	6	
L Buck		8	North	10	
M W Oak		20	S 30 W	9	
B Oak		22	North	33	
N Sugar		13	Corner		" N to O Broken; Buck, Oak, Sugar 3rd ratio.
n Water Buck		3	S 30 W	21	
Maple		8	S 37 W	47	
O B Oak		24	S 60 W	22	" O to P ditto
Sugar		10	S 25 E	41	
o Hickory		10	S 70 W	23	
Sugar		4	S 40 E	11	
P Dogwood		3	West	5	" P to Q Level, 2nd ratio; Buck, Oak Hickory.
Hickory		6	30 E	11	
P Poplar		22	S 35 E	9	
Buck		10	S 55 W	9	
Q W Oak		20	S 38 W	11	" Q to R
B Oak		22	S 4 E	21	
q Sugar		11	South	8	
Sugar		12	S 74 W	8	
R Buck		12	S 39 E	6	" R to S
Sugar		9	S 1 E	31	
r Poplar		7	S 52 W	17	
Buck		16	S 29 E	37	
S W Oak		14	S 1 W	30	" S to T
W Oak		14	S 21 W	7	
t Poplar		42	S 19 W	29	
W Oak		36	S 28 E	25	
T W Oak		22	S 20 E	20	" T to U
Buck		8	S 6 W	31	
u Buck		13	West	8	
W Oak		30	East	23	
U B Oak		16	S 42 W	27	" U to V
Shonwood		7	S 65 E	35	
u W Oak		11	S 31 W	19	
W Oak		24	S 79 E	36	
V W Oak		36	S 12 W	23	" V to A
Buck		13	S 72 E	32	
v Sycamore		9	S 19 E	7	
Elm		8	S 79 W	39	

Interior sectional corners described

Sectional Corners	Bearing true	Inches diam	Course true bear	Links dist
7. 3. 7. 13	Dogwood	4	Corner	
5. 6. 7. 8	Sugar	12	S 45 E	9

Quarter section corners described.

From and to	Bearing true	Inches diam	Course true bear	Links dist
I to R at	Poplar	14	S 60 W	25
	B Oak	40	S 65 W	8
H to S at	Gum	12	S 68 E	25
	Maple	14	S 4 W	17
G to T at	Buck	10	S 65 W	13
	Buck	10	S 27 W	10
E to U at	Hickory	14	S 40 W	41
	W Oak	28	S 63 W	33
D to V at	Sugar	8	S 35 E	24
	No other trees near			
F to B at	Gum	8	S 40 E	5
	Gum	10	West	29
	Buck	4	S 50 W	3
	Buck	10	S 41 E	17



Townships N°VI and VII North, Range N°XIII East.

Surveyed by Stephen Ludlow 1807.

Quality of the land on the interior sectional lines.

Between Sections.	quality	Between Sections.	quality
30. 31.	Level; Bush, & Oak &c	5. 8.	Broken; Bush, & Oak &c
18. 19.	ditto	6. 7.	ditto
7. 15.	ditto	5. 6.	ditto
19. 30.	Broken; Bush, & Oak &c	17. 18.	Timber; Oak, Poplar, &c
7. 8.	ditto		